Since last meeting

- Readout software running on raspberry PI
- Few changes to firmware to improve readout
- Pulsed readout working

Readout, Pulse width 16 nS, 56 mV



Future Schedule

- New STURM2 DC, IRS3C DC and common power board in 1 – 2 weeks
- RF Signal splitter to help with testing
- tuning and cleaning firmware this week
- Start looking into ethernet / optical connection