

IRS Chip Testing Report

09/09/2010

Chih-Ching Chen
and Chiu-Chuan
Ming-Yuan


status of the tests we discussed in Hawaii

- Find a data value set for testing
- Replace a new IRS chip
- Voltage cal.
- Storage access testing for all 32K (ongoing)

Will do:


- Sample timing calibration for one channel
- Sampling timing calibration by Avtech pulse
- Change CMPbias resister

Replace a new IRS



testing details and difficulties

- The CH0-CH2 signal are bad after 64 sampling points in new IRS chip. New TSA value?



questions

- The IRS testing board layout file