



TOF Electronics – status as of the End (MTS1877 → COPPER TMC readout)






Electronics Hut – Floor 2

## What to keep? (Discussion)



to CDC

(b) TOF Signal readout



Delayed by 2.2ms~30ms

- Trigger ?
- HV if possible?
- TOFFEE aren't easy to re-use

to GDL

• Have no need for TSCs...