


# Shock (G), Temperature (T) and Humidity (H) - At the Quartz Bar Box -



# Shock (G), Temperature (T) and Humidity (H) - At the Backside of the Crate Lid -

