

| Carrier 02 # | Location | Hand Soldered? | | Carrier 13 # | Location | Missing M0-M34 ADG3248BKSZ | Missing A0-A31 OPA846 |
|-------------------------------------|-------------------|---------------------|--|--------------|-------------------|-------------------------------|--------------------------|
| 1 | in SLAC | No | | 1 | in c13 bin | No | No |
| 2 | in SLAC | No | | 2 | in c13 bin | 9 missing on front | No |
| 3 | being used in lab | No | | 3 | in c13 bin | 19 missing on front | No |
| 4 | in c02 bin | Yes, 16 middle amps | | 4 | in c13 bin | 19 missing on front | No |
| 5 | in c02 bin | No | | 5 | in c13 bin | No | No |
| 6 | in c02 bin | No | | 6 | in c13 bin | No | No |
| 7 | in c02 bin | No | | 7 | in c13 bin | No | No |
| 8 | in c02 bin | Yes, 24 amps | | 8 | in c13 bin | No | Missing all amps |
| 9 | in c02 bin | Yes, 16 middle amps | | 9 | in c13 bin | No | No |
| 10 | being used in lab | No | | 10 | in c13 bin | No | Missing all amps |
| 11 | being used in lab | No | | 11 | being used in lab | No | No |
| 12 | MISSING | No | | 12 | being used in lab | No | No |
| Last updated: 02/26/2013 | | | | | | | |